
1 of 16




F I G. 1




F I G. 2

2 of 16





F I G. 3



F I G. 4

3 of 16





F I G. 6

5 of 16

0	1	5	6	14	15	27	28
2	4	7	13	16	26	29	42
3	8	12	17	25	30	41	43
9	11	18	24	31	40	44	53
10	19	23	32	39	45	52	54
20	22	33	38	46	51	55	60
21	34	37	47	50	56	59	61
35	36	48	49	57	58	62	63

(A)

0	4	6	20	22	36	38	52
1	5	7	21	23	37	39	53
2	8	19	24	34	40	50	54
3	9	18	25	35	41	51	55
10	17	26	30	42	46	56	60
11	16	27	31	43	47	57	61
12	15	28	32	44	48	58	62
13	14	29	33	45	49	59	63

(B)


0	1	2	3	10	11	12	13
4	5	8	9	17	16	15	14
6	7	19	18	26	27	28	29
20	21	24	25	30	31	32	33
22	23	34	35	42	43	44	45
36	37	40	41	46	47	48	49
38	39	50	51	56	57	58	59
52	33	54	55	60	61	62	63


F I G. 7


6 of 16


X14 X15 X16	0 0	0						(C)	12 6 11								( <u>n</u> )						о С	o - -	
X11   X12   X13	X21 X22 0	0 0 V	X41 0 0	X51 X52	Xe1	X7:			9   1   2	2 4	3 7	8	9 13	<b>7</b> 4	15		X14 X15 X16								(E)
0	0	0	0	0	0	0	0										X13	Miller	Mexica						
0	0	0	0	0	0	0	0										X12	X22	0	0	X52				
X16	0	0	0	0	0	0	0		X16								X:	X21	X34	X41	X51	X61	X71		
X15	0	0	0	0	0	0	0	(A)	X15	0						á	n n								
X14	0	0	0	0	0	0	0	)	X14	0	0						シ					•			
X13	0	0	0	0	0	0	0		X13	0	0	0													
X12	X22	X32	X42	X52	0	0	0		X12	X22	X32		X52		Supplies										
X11	X21	X31	X41	X51	X61	X71	0		X11	X21	X31	X41	X51	X61	X7.1										


7 of 16




















F I G. 14





F I G. 16a



F I G. 16b